

CLASSIFIED MESSAGE

25X1
 ORIG
 UNIT
 EXT
 DATE : 28 JAN 1963

S-E-C-R-E-T

ROUTING

1	COMMO/OSA	4	DD/R	
2	DAD/OSA	5	DD/P	
3	AD/OSA	6	C/FE	
C/ME				
ADMIN/OSA				
KSB/OSA				
C/PS				
RB/OSA				
PROCEDURE		DEFERRED	PRIORITY	INITIALS
	IX	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

25X1 TO :
 FROM: DIRECTOR
 CONF: OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)
 INFO: S/C (17)

OUT42883

DTG 1655Z 28 JAN 63

25X1 TO: INFO

CITE

2337

COMMO

25X1 FOLLOWING IS TECH FEEDBACK

MISSION 3215:

1. P BAND NOISY FROM "AC OFF". L BAND AND X BAND QUIET. S BAND HAD REGULAR NOISE, PROBABLY MOTOR ABOARD PLANE.
2. TAPE BOTH RECORDERS RAN OUT EARLY. REQUEST IN FUTURE IF TAPE CUT OFF BEFORE "AC OFF", THIS TIME BE INCLUDED IN DATA SHEETS.
3. ANALYST REQUESTS WIRING BE CHECKED ASSURE X AND S BAND SWITCHING RIGHT AND LEFT PROPERLY AND TOGETHER.

END OF MESSAGE

25 YEAR RE-REVIEW

25X1 CHIEF, OSA/COMMO

COORDINATING OFFICERS

S-E-C-R-E-T

RELEASING OFFICER

GROUP 1 - Excluded from
automatic downgrading
and declassification.

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.